

PRODUCT DATA SHEET

## SELECTION & SPECIFICATION DATA

Generic Type | Trowel applied vinyl ester lining

# Description

A high-performance, highly chemical resistant lining that uses several layers of thermosetting, filled vinyl ester resin to build up protection on metal and concrete. It is well suited for chemical manufacturing or processing operations. Used as a component of a system with fiberglass reinforcement, the separate elements lose their individual identity and become a single, monolithic lining.

- · Exceptional resistance to inorganic and organic acids
- Excellent caustic and alkaline solution resistance
- · Excellent abrasion resistance and hardness

## **Features**

- FDA compliant
- · Low permeability
- Conductive system available (Protecto-Glass 865)
- · Plating room floors
- · Food processing

### **Typical Uses**

- Concentrated acid spills
- · Acid neutralization
- · Caustic handling areas

Color | Clear (0000)

**Primer** | Primer 27 series

**Application Thickness** When blended with the appropriate filler, mortar will yield a minimum thickness of 1/16".

Solids Content | By Volume 74%

Dry Temp. Resistance

Continuous: 200°F (93°C) Non-Continuous: 250°F (121°C)

- · Inorganic Acids
- · Organic Acids

#### **Chemical Resistance**

- Alkali Solutions
- Oils
- · Salts

## **Application**

For maximum performance, all metal surfaces should be primed.

Concrete must be primed to aid in the "wetting out" required for good bonding.

PRODUCT DATA SHEET



## SUBSTRATES & SURFACE PREPARATION

Concrete must be mechanically prepared to remove surface laitance. Oils, grease or other contaminant must be removed prior to surface preparation. Concrete must be free of curing compounds and form release agents. Surface texture should be similar to 40-60-grit sandpaper or the visual standard, CSP-5 or higher from the International Concrete Repair Institute with exposed pea gravel. The prepared surface should have a nominal tensile strength of 250 PSI per ASTM D4541.

#### Concrete

All concrete substrates must be checked for moisture prior to product application using the Plastic Sheet Test, ASTM D4263.

Additional surface preparation will be required if a 40-60 grit texture with exposed pea gravel is not achieved and the surface laitance not completely removed with the first mechanical preparation procedure.

Primer 27 is recommended to be used to promote better adhesion or as a holding primer in immersion service.

#### **Ferrous Metal**

Immersion and heavy spillage service: White Metal, SSPC SP 5 or NACE No.1, minimum 3.0 mil profile.

<u>Heavy non-immersion service (i.e. fumes and spillage):</u> Near white, SSPC SP 10 or NACE No.2, minimum 2.0 mil profile.

Atmospheric service: Commercial SSPC SP 6 or NACE No.3, minimum 2.0 mil profile

#### Non-Ferrous Metals

#### Must be primed with Primer 27 for immersion service.

Prepare by abrasive blasting to SSPC-SP 17 Thorough Abrasive Blast to a minimum of 3 mils (75 microns) dense angular anchor profile.

## PERFORMANCE DATA

## All test data was generated under laboratory conditions. Field testing results may vary.

Test Method	Results	
Coefficient of Expansion ASTM C531	12-15 x 10-6 in./in./⁰F	
Compressive Strength ASTM C579	12,500 PSI	
Flexural Strength ASTM C580	8,600 PSI	
Shore D Hardness ASTM D2240	75-80	
Tensile Bond Strength ASTM D7234	Cohesive failure of concrete	
Tensile Strength ASTM C307	2,400 PSI	

Tested as a full system with Protecto-Coat 800 as a topcoat.

#### MIXING & THINNING

Mixing

Add the correct amount of PH- 1 Hardener to the Part A. Mix thoroughly for 2-3 minutes. Add 18-25 lbs. of G-1 Filler/gal. Mix well and apply a 1/16" thick basecoat, using a plasterer's trowel.

PH-1 Hardener Ratio:

Ratio

3-4 oz/gal of PH-1 @ 60°F-70°F (15°C-21°C) 2-3 oz/gal of PH-1 @ 70°F-90°F (21°C-32°C)

Pot Life

40-50 minutes @ 50°F-70°F (10°C-21°C) 20-30 minutes @ 70°F-90°F (21°C-32°C)



PRODUCT DATA SHEET

## APPLICATION PROCEDURES

After mixing the Part A, Part B, and G-1 filler per the mixing instructions, apply approximately 1/16" (~60 mils) thick basecoat to a smooth, even finish using a trowel.

## Adding reinforcement and saturant:

Before the basecoat begins to cure, press one layer of 1 oz glass mat into the wet basecoat. Overlap all edges by 1 inch. Use a stiff, natural bristle brush or short nap roller and press the mat firmly into the basecoat, using a technique similar to hanging wallpaper, to remove all air pockets and wrinkles.

Saturate the reinforcement by mixing Part A and B only, do not add the filler, to make a neat resin mixture. Using a short nap roller, roll vigorously until the mat has lost its white color and turns translucent, paying special attention to overlaps and corners. Use enough resin to wet out the mat, but do not allow the saturant to puddle. If needed, roll the wet reinforcement with a ribbed roller to remove any trapped air or wrinkles. Allow the basecoat and reinforcement application to dry.

Trowel

\_

#### **Topcoat Application:**

Before applying the topcoat, the troweled basecoat, fiberglass mat, and saturant layers must dry thoroughly to allow for the surface to be ground to provide profile for successive coats and remove any high spots or protrusions. Grinding must draw dust. Use caution not to grind through the reinforcing layer, then solvent wipe the entire surface.

Examine the reinforcement for any air bubbles or blisters. If these are present, they must be cut out and repaired, using the procedure above. Rough overlaps and protruding reinforcement strands must be abraded and smoothed. The topcoat will emphasize any imperfections in the reinforcement. Excessive blistering of the basecoat reinforcement may indicate inadequate rolling or too little saturant. Apply topcoat according to the corresponding product data sheet.

## **APPLICATION CONDITIONS**

Condition	Material	Surface	Ambient	Humidity
Minimum	60°F (16°C)	60°F (16°C)	60°F (16°C)	0%
Maximum	80°F (27°C)	110°F (43°C)	110°F (43°C)	90%

Substrate temperature must be 5°F (3°C) above the dew point.

# **CURING SCHEDULE**

Surface Temp.	Minimum Recoat Time	Chemical Service	Maximum Recoat Time
50°F (10°C)	12 Hours	4 Days	5 Days
75°F (24°C)	4 Hours	2 Days	4 Days
90°F (32°C)	3 Hours	24 Hours	3 Days

## **CLEANUP & SAFETY**

Cleanup | Use S-10 Cleaning Solvent or Carboline Thinner 2 to clean tools and equipment.

Safety

Read and follow all caution statements on this product data sheet and on the SDS. Employ normal safety precautions. Keep container closed when not in use.

Ventilation

Ventilation must be used during and after application until the coating is cured. The ventilation system should be capable of preventing the solvent vapor concentration from reaching the lower explosion limit for the solvents used. User should test and monitor exposure levels to insure all personnel are below guidelines. Use MSHA/NIOSH approved air respirators as needed.

PRODUCT DATA SHEET



#### CLEANUP & SAFETY

Caution

Fire and explosion hazards: This product contains less than 1% volatile components, however, vapors are heavier than air and can travel long distances, ignite and flash back. Eliminate all Ignitions sources. Keep away from sparks and open flames. All electrical equipment and installations should be made and grounded in accordance with the National Electric Code. In areas where explosion hazards exist, workers should be required to use non-ferrous tools and wear conductive and non-sparking shoes.

# PACKAGING, HANDLING & STORAGE

#### 1 Gallon Kits:

Part A: 0.97 Gallons (in a 3.5 gal pail) PH-1 Hardener: 4 oz (in a plastic bottle)

### **Packaging**

5 Gallon Kits:

Part A: 4.85 Gallons (in a 5 gal pail) PH-1 Hardener: 16 oz (in a plastic bottle)

G-1 Filler is sold separately in a 50 lb. bag.

Part A: 3 months

PH-1 Hardener: 6 months G-1 Filler: 36 months

**Shelf Life** 

Material can not be returned after purchase.

#### Storage

All Dudick products classified by DOT with either white, yellow or red labels must not be mixed or stored together as an explosive reaction can occur.

All products should be stored in a cool, dry area, away from open flames, sparks, or other hazards.

# Shipping Weight

1 gallon kit: 14.6 lbs (Approximate) 5 gallon kit: 50.5 lbs

## WARRANTY

To the best of our knowledge the technical data contained herein is true and accurate on the date of publication and is subject to change without prior notice. User must contact Carboline Company to verify correctness before specifying or ordering. No guarantee of accuracy is given or implied. We guarantee our products to conform to Carboline quality control. We assume no responsibility for coverage, performance, injuries or damages resulting from use. Carbolines sole obligation, if any, is to replace or refund the purchase price of the Carboline product(s) proven to be defective, at Carbolines option. Carboline shall not be liable for any loss or damage. NO OTHER WARRANTY OR GUARANTEE OF ANY KIND IS MADE BY CARBOLINE, EXPRESS OR IMPLIED, STATUTORY, BY OPERATION OF LAW, OR OTHERWISE, INCLUDING MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. All of the trademarks referenced above are the property of Carboline International Corporation unless otherwise indicated.