

# Product Case History



## PROJECT DESCRIPTION:

The tank had previously been over-coated multiple times, as recent as 2007. The owner chose to do a complete removal of the existing coatings. The inside had an elastomeric polyurethane. Reactamine 760 was used to touch up areas of failure.

## Marion Municipal Ground Storage Reservoir

**LOCATION:** Marion, LA, United States

**DATE OF APPLICATION:** September 2016

**MARKET:** Water & Wastewater

**TYPE:** Rehabilitation

**OWNER:** City of Marion, IA

**PROJECT SIZE:** 1 Tanks

**AREA COATED:** Tank Exterior

PRODUCTS: Carbozinc 859, Carboguard 60, Carbothane 134 HG

**AREA COATED:** Tank Interior

PRODUCTS: Reactamine 760